



3140 Mounted Planters: Dimensions

Feature/Option	12R 30	12R 36-40	12R 38-40	16R 30
Width - Transport	16' 1" without markers 17' 9" with markers	18' 6" without markers 19' 6" with markers	21' 1" without markers 22' 2" with markers	21' 1" without markers 23' 0" with markers
Width - Planting	30' 0"	37' 4"	40' 0"	40' 0"
Length - Transport	---	---	---	---
Length - Planting	---	---	---	---
Height - Transport	12' 6" without markers (lower link pins at 42" height) 15' 6" with markers	12' 6" without markers (lower link pins at 42" height) 15' 6" with markers	12' 6" without markers (lower link pins at 42" height) 15' 6" with markers	12' 6" without markers (lower link pins at 42" height) 15' 6" with markers
Height - Planting (Bulk Fill Only)	---	---	---	---
Weight - Base Machine	6,236 lbs. Conventional/ Mechanical Meters 6,794 lbs. Conventional/Vacuum Meters"	6,541 lbs. Conventional/ Mechanical Meters 7,127 lbs. Conventional/Vacuum Meters	6,621 lbs. Conventional/ Mechanical Meters 7,214 lbs. Conventional/Vacuum Meters	7,480 lbs. Conventional/ Mechanical Meters 8,109 lbs. Conventional/Vacuum Meters